

Daikin FDXM35F9 / RXM35N9



?????????: ??? ????????????? ?????

???????? : Daikin FDXM35F9 / RXM35N9


1544 €

????? ??? ??????? ??? ?? ???????

????????????Daikin

?????????
 ?????????? ???????? Daikin FDXM35F9 / RXM35N9 BRC1H51K/SAW

- [illegible]



??????????????
 ❏ ???? - BTU: 11.605
 ❏ ???? - ?????????? ?????: A
 ❏ SEER: 5.26

?????????? ?????. M??????(mm): 200/750/620
 ?????? ??????? ?????.?????????: 53/35/31 dB

 ???????? - BTU: 15.360
 ???????? - ?????????? ?????: A
 SCOP: 3.88

?????????? ?????. M??????(mm): 550/765/285
 ?????? ??????? ?????.?????????: 61 dB

????? ??????

??? ?????????? ?????????????? ??? ?? ?????? ??????.